


2nd QTR  
5

FUGITIVE OR SMOKE EMISSION INSPECTION  
EPA METHOD 22 for OUTDOOR LOCATION

Company Site Company Rep	<u>Waste Management</u> <u>Cottonwood Hills</u> _____	Observer Affiliation Date	<u>Mike McElvain</u> <u>WM</u> <u>5.16.17</u>
Sky Conditions Precipitation	<u>Partly Cloudy</u> <u>NONE</u>	Wind Direction Wind Speed	<u>South</u> <u>5-10 mph</u>
Process Unit* Current Monitoring Frequency *(Flare, Solidification, Crusher, Diesel Engine)	<u>Open Flare</u> <u>Quarterly</u> _____	Operational Status	<u>ON</u>

Sketch process unit. Indicate observer position relative to the source. Indicate potential emission points and/or actual emission points.



OBSERVATIONS

	Clock Time	Observation period duration (min:sec)	Accumulated emission time (min:sec)	
Begin Observation	<u>1315</u>	<u>10 min</u>	<u>Ø</u>	
	<u>1330</u>	<u>10 min</u>	<u>Ø</u>	
	<u>1345</u>	<u>10 min</u>	<u>Ø</u>	
	<u>1400</u>	<u>10 min</u>	<u>Ø</u>	
	<u>1415</u>	<u>10 min</u>	<u>Ø</u>	
	<u>1430</u>	<u>10 min</u>	<u>Ø</u>	
	<u>1445</u>	<u>10 min</u>	<u>Ø</u>	
	_____	_____	_____	
End Observation	<u>1445</u>	<u>60 minutes</u>	<u>Ø</u>	Totals

Description of corrective action:

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

Page 2